## Διαδικασία ρύθμισης παραμέτρων wifi σε Xprinters με το POS PRINTER TEST V3.2

**1.** Συνδέουμε τον εκτυπωτή με USB ή με καλώδιο δικτύου. Πατάμε Print για να βεβαιωθούμε ότι η σύνδεση είναι επιτυχής και στην συνέχεια επιλέγουμε Advanced.

	-2				
Port Select	COM OUSB	ONET	Printer Type O POS-58	OPOS-76	POS-80
LPT Settings	COM Settings COM3 ~	128000	~ R1	rs ~	1
NET Set	<b></b>				
Local IP:	192 . 168 . (	0 . 77	Refresh	Auto Set I	p
Printer IP:	192 . 168 . (	0 . 241	Connect	Ping	
New IP:	192 . 168 .	1 . 100	Set New IP	NetMonite	pr
New ID:	0.0.0	0.0	New ID	(Set last four	ID)
Content: NC 1 2 Velcome to use the eceipt printer con	0. Rep: 1	HEX Clear	ar AutoSeno	d Cyc 50 onal POS	0 ms CutPaper
Content NC 1 2 Velcome to use the celpt printer con	D. Rep: 1	HEX Clea	ar AutoSend	d Cyc 50	0 ms CutPaper Print CutPaper Open cash drav
Content: NC 1 2 Velcome to use the eceipt printer con	0. Rep: 1	HEX Clea	ar AutoSend	d Cyc 50	0 ms CutPaper Print Cut Paper Open cash drav Traditional
Content NC 1 2 Velcome to use the eceipt printer con	D. Rep: 1	HEX Clea	ar AutoSend	d Cyc 50	0 ms CutPaper Print Cut Paper Open cash draw Traditional Driver Print
Content NC 1 2 Welcome to use the eceipt printer content of the second	D. Rep: 1	HEX Clea	ar AutoSend	d Cyc 50	0 ms CutPaper Print Cut Paper Open cash draw Traditional Driver Print Advanced
Content ONC 1 2 Velcome to use the eceipt printer con	D. Rep: 1	THEX Clear	ar AutoSend	d Cyc 50	0 ms □ CutPaper Print Cut Paper Open cash drav Traditional Driver Print Advanced 中文简体

## 2. Στην παρακάτω advanced καρτέλα επιλέγουμε SetNet

Advanced		9.90	i Chinese	×
H Parameter Settings:	Print H	Set Delta	5 ~	
Code page Settings:	PrintCodePage	SetCodePage	0	
NV Logo Test	NV Download (1c 70)	NV Download (1d 28)		
Barcode Printing test	Print BarCode	UPC_A ~	129 ~	Height
P76 Buzzer Settings:	Set Buzzer	OFF ~	Set Paper saving	
P76 Density Settings:	Set	NORMAL ~		
P80 Black sens:	Set Sensitivity	12 ~	12 ~	SensH
baud rate settings:	Set BaudRate	19200 ~	(Only P58 and P76E)	
DIP Settings:	Set P58 DIP	Set P80 DIP	Set P76 DIP	
2D Barcode test	Print 2D Barcode			
Net Settings:	Set Net	Set Bluetooth		
USB MODE Settings:	USB Printing	Virtual COM		
Black Mark Settings:	Set 80 BlackMark	Set 76 BlackMark		
File data send	Open File send			
Cut With Beep	Cut With Beep Set	~		
InputBox Codepage:	737 - Greek(DOS)	~	SET	

**3.** Εισάγουμε στο παρακάτω παράθυρο τις ρυθμίσεις IP και wifi και επιλέγουμε SET ALL. Ο εκτυπωτής παράγει σύντομους ήχους επιβεβαίωσης και βγαίνει μήνυμα στην οθόνη ότι οι ρυθμίσεις καταχωρήθηκαν. Προσοχή στο πεδίο Wifi cmd όπου διορθώνουμε την πρώτη επιλογή με την σωστή IP που θέλουμε.

et Settings			:
Net Settings	192 . 168 . 6 . 192	SetIPAddr	
NetMask	255 . 255 . 255 . 0	SetNetMask	
GateWay	192 . 168 . 6 . 1	SetGateWay	
	Set above contents		POS
WIFI Settings			Set All
SSID:	ICS GUEST		
WIFI Key	icsguest		
Кеу Туре	WPA2_AES_PSK	~	Return
	Set above contents		
WIFI CMD:	AT+SIP=1,192.168.2.106	~	
	CMD Set		

Σε κάποιες περιπτώσεις όπου έχουμε να κάνουμε με παλαιότερους εκτυπωτές ίσως χρειαστέι παλιότερη version του Printer Test Tool