

The reason and solution of PL2303TA not working on Win 11 system.

It is available to Install PL2303_Prolific_DriverInstaller_v1200 driver as version number below.




Since the Win11 system forces regular automatic updates, it also automatically updates the driver. When the system is updated, the driver will be upgraded to the prohibited version provided by the manufacturer as below:




The solution is to use other tool to disable this driver to follow the system update to upgrade to the latest version. Tool: WuMgr. How to use:

1. Install PL2303_Prolific_DriverInstaller_v1200 driver.
2. Run the WuMgr tool and follow the steps below:



If your driver already is the latest version:

1. Access in device manager to uninstall the device (Right-click to uninstall the device)
2. Reinstall the driver and disable the update.



卸载设备

