



Capacitive screen USB interface upgrade program guide

Step 1: Make sure the USB cable is plugged into the machine's USB port and the control panel is connected to the touch screen.






Step 2: Open the burning tool“ ILITEK USB...”:




Then click the "Search" button, the following picture will appear


When this line of information appears, the entire connection is normal, then you can upgrade




Step 3: Click the “Load Hex” button and select the file to be upgraded (the file with the suffix Hex) as shown below:





After the loading is complete, click the confirmation button, as shown below:



Step 4: Click the “Upgrade” button, and the system will start to upgrade. After about 25 seconds, the upgrade will be successful, as shown below:



The upgrade progress is displayed as shown below:



Click OK, the entire upgrade process is completed, you can connect with the host test res

